

Full Throttle Promotions Stock Truck Rules 2021

1. All trucks must have stock equipment. No pre bending. Trucks to be “prepared” the same way as stated in the “General / Standard Rules”. Seat bar, dash bar & door bars inside are strongly recommended.
2. 1/2- or 3/4-Ton American made pickup truck only. No 4 doors. You can use a 4-wheel drive if front drive shaft is removed.
3. Truck bumpers on trucks, max bumper height of 30” with a min of 24 to top of bumper. Front on front, rear on rear, for same style truck. No 1 or 2-ton grain truck bumpers. ½ ton & ¾ ton only. Can be welded on with no extra metal. In addition to the factory bumper skin you will be allowed a tube from frame horn to frame horn behind skin. Front only, max size of tube can be 3x3 ¼ inch thick. No wider then the front frame horns.
4. No additional plating allowed in box or cab. Battery box and fuel tank no longer than necessary. Not for reinforcing.
5. Any air inflated tire can be used up to 16.5”. No solid, or foam filled tires. Stuffed tires allowed. Aftermarket 8” dia. multi lug rim centers are allowed, rest of rim must remain stock.
6. Hood can be chained, wired, or bolted down. Maximum 6 spots per hood. Only 2 bolts can go to or thru frame at radiator support. Bolt must go from frame straight up (not angled) and can have top 5 inches welded to core support. Bolt can go thru bottom of core support only, near frame. Max bolt size 3/4”, max washer 5” x ¼ “rest of bolts thru tin only.
7. Box may be mounted to frame with bolts or U-bolts. With max of 8 places (includes original bolts in box that remain). Cab may be mounted to frame with bolts or U-bolts. With max of 8 places including radiator supports and factory mounts. You may bolt box and cab together with up to 4 bolts, and you may weld a short flat strap between box and cab. (1/4” x W x 12” max) one on each side. Max bolts and washers are ¾ bolts & ¼ x 8” washer. Roll over bar strongly recommended, mount in front of box, as close as possible to cab. No wider than frame, maximum height is to top of cab. Can bolt or weld to box, or to washers that hold box to frame. Or can weld to top of frame. Maximum distance is 2’ back on floor with kicker brace. Can attach to roof in two spots using 1/4x3” strapping, with a max of ¾ inch bolts.
8. Tailgate must be welded to box 12” max per side and 12inches of weld will be allowed from tailgate to box floor. (not to frame or bumper.) If no rear bumper, tail gate can be slid down so that bottom of tail gate is at bottom of frame rail. If done this way, you must have two wires or chain around bottom of box floor thru tailgate. You will be allowed 2” of weld per rear frame horn to attach to tailgate.
9. A-Arms can be welded down with 2 - 2” x ¼” straps on each side of A-Arms, and nothing additional a ¼” tube can be bolted in place next to front shocks only to gain height. Cannot be welded in or used for reinforcement or tied to anything additional. Bumper height must comply. Trucks with leaf springs front or back can have 4 spring clamps per side.

